

**Record of Orders made by the  
Registered Fire Service Installation Contractors Disciplinary Board (2017)**

<b>Name of Registered Fire Service Installation Contractor</b>	<b>Class / Registration No.</b>	<b>Effective Date of Order</b>	<b>Order</b>	<b>Government Notice No.</b>	<b>Link to Government Notice (with Case Details)</b>
Wah Shing Building Contractors Limited	RC1/439 RC2/612	5.8.2017	Reprimanded	G.N. 6173	<a href="http://www.gld.gov.hk/egazette/pdf/20172133/egn201721336173.pdf">http://www.gld.gov.hk/egazette/pdf/20172133/egn201721336173.pdf</a>
Far East Engineering Services Ltd.	RC1/153 RC2/250	21.6.2017	Reprimanded	G.N. 4874	<a href="http://www.gld.gov.hk/egazette/pdf/20172128/egn201721284874.pdf">http://www.gld.gov.hk/egazette/pdf/20172128/egn201721284874.pdf</a>
HUI HAM SO trading as Sun Tai Company	RC2/602	22.6.2017 5.7.2017	Removed from the register of Class 2 Fire Service Installation Contractors for 14 days	G.N. 4875	<a href="http://www.gld.gov.hk/egazette/pdf/20172128/egn201721284875.pdf">http://www.gld.gov.hk/egazette/pdf/20172128/egn201721284875.pdf</a>
RNB Engineering Hong Kong Limited	RC1/423 RC2/597	22.6.2017	Reprimanded	G.N. 4876	<a href="http://www.gld.gov.hk/egazette/pdf/20172128/egn201721284876.pdf">http://www.gld.gov.hk/egazette/pdf/20172128/egn201721284876.pdf</a>
Wylam's Services Limited	RC1/135 RC2/266	22.6.2017	Reprimanded	G.N. 4877	<a href="http://www.gld.gov.hk/egazette/pdf/20172128/egn201721284877.pdf">http://www.gld.gov.hk/egazette/pdf/20172128/egn201721284877.pdf</a>
Chavez Engineering Ltd.	RC2/550	17.1.2017 -30.1.2017	Removed from the register of Class 2 Fire Service Installation Contractors for 14 days	G.N. 707	<a href="http://www.gld.gov.hk/egazette/pdf/20172106/egn20172106707.pdf">http://www.gld.gov.hk/egazette/pdf/20172106/egn20172106707.pdf</a>
Marvel Fire Engineering Co. Ltd.	RC1/235 RC2/381	19.1.2017 -1.2.2017	Removed from the registers of Class 1 and Class 2 Fire Service Installation Contractors for 14 days	G.N. 708	<a href="http://www.gld.gov.hk/egazette/pdf/20172106/egn20172106708.pdf">http://www.gld.gov.hk/egazette/pdf/20172106/egn20172106708.pdf</a>
Kin Ying Contracting Limited	RC1/383 RC2/544	19.1.2017 -1.2.2017	Removed from the registers of Class 1 and Class 2 Fire Service Installation Contractors for 14 days	G.N. 709	<a href="http://www.gld.gov.hk/egazette/pdf/20172106/egn20172106709.pdf">http://www.gld.gov.hk/egazette/pdf/20172106/egn20172106709.pdf</a>

**Record of Orders made by the  
Registered Fire Service Installation Contractors Disciplinary Board (2017)**

<b>Name of Registered Fire Service Installation Contractor</b>	<b>Class / Registration No.</b>	<b>Effective Date of Order</b>	<b>Order</b>	<b>Government Notice No.</b>	<b>Link to Government Notice (with Case Details)</b>
LAU Siu-yung trading as Enterich Fire Services Engineering Co.	RC1/301 RC2/450	20.1.2017 -26.1.2017	Removed from the registers of Class 1 and Class 2 Fire Service Installation Contractors for 7 days	G.N. 710	<a href="http://www.gld.gov.hk/egazette/pdf/20172106/egn20172106710.pdf">http://www.gld.gov.hk/egazette/pdf/20172106/egn20172106710.pdf</a>