

**Record of Orders made by the
Registered Fire Service Installation Contractors Disciplinary Board for the Past 5 Years**

| Name of Registered Fire Service Installation Contractor | Class / Registration No. | Effective Date of Order | Order | Government Notice No. | Link to Government Notice |
|--|---------------------------------|--------------------------------|--|------------------------------|---|
| Firetech Services Limited | RC1/0436 RC2/0610 | 25.10.2022 – 5.12.2022 | Removed from the registers of Class 1 and Class 2 Fire Service Installation Contractors for 6 weeks | G.N. 6495 | https://www.gld.gov.hk/egazette/pdf/20222645/egn202226456495.pdf |
| Yearman Industrial Ltd. | RC1/0265 RC2/0410 | 25.10.2022 – 24.12.2022 | Removed from the registers of Class 1 and Class 2 Fire Service Installation Contractors for 2 months | G.N. 6496 | https://www.gld.gov.hk/egazette/pdf/20222645/egn202226456496.pdf |
| Bright Wong Engineering Co. | RC1/0137 RC2/0096 | 25.10.2022 – 24.12.2022 | Removed from the registers of Class 1 and Class 2 Fire Service Installation Contractors for 2 months | G.N. 6497 | https://www.gld.gov.hk/egazette/pdf/20222645/egn202226456497.pdf |
| Shin Fai Engineering Services Limited | RC1/0548 RC2/0726 | 25.10.2022 – 24.12.2022 | Removed from the registers of Class 1 and Class 2 Fire Service Installation Contractors for 2 months | G.N. 6498 | https://www.gld.gov.hk/egazette/pdf/20222645/egn202226456498.pdf |
| Wai Kong Fire Engineering Company Limited | RC1/0132 RC2/0264 | 14.6.2022 – 13.9.2022 | Removed from the registers of Class 1 and Class 2 Fire Service Installation Contractors for 3 months | G.N. 3528 | https://www.gld.gov.hk/egazette/pdf/20222627/egn202226273528.pdf |
| E W Consultant Limited | RC1/0490 RC2/0663 | 14.6.2022 – 4.7.2022 | Removed from the registers of Class 1 and Class 2 Fire Service Installation Contractors for 3 weeks | G.N. 3529 | https://www.gld.gov.hk/egazette/pdf/20222627/egn202226273529.pdf |
| LEUNG Kam-hing | RC3/0718 | 14.6.2022 – 13.8.2022 | Removed from the register of Class 3 Fire Service Installation Contractors for 2 months | G.N. 3530 | https://www.gld.gov.hk/egazette/pdf/20222627/egn202226273530.pdf |

**Record of Orders made by the
Registered Fire Service Installation Contractors Disciplinary Board for the Past 5 Years**

| Name of Registered Fire Service Installation Contractor | Class / Registration No. | Effective Date of Order | Order | Government Notice No. | Link to Government Notice |
|--|---------------------------------|--------------------------------|--|------------------------------|---|
| Yiu Lam Engineering Services Company Ltd. | RC1/0409 RC2/0579 | 15.1.2022 – 25.3.2022 | Removed from the registers of Class 1 and Class 2 Fire Service Installation Contractors for 10 weeks | G.N. 539 | https://www.gld.gov.hk/egazette/pdf/20222604/egn20222604539.pdf |
| Easy Profit Engineering Limited | RC1/0280 RC2/0424 | 15.1.2022 – 14.3.2022 | Removed from the registers of Class 1 and Class 2 Fire Service Installation Contractors for 2 months | G.N. 538 | https://www.gld.gov.hk/egazette/pdf/20222604/egn20222604538.pdf |
| Lap Fung Fire Engineering Company Ltd. | RC1/0230 RC2/0375 | 15.1.2022 – 14.3.2022 | Removed from the registers of Class 1 and Class 2 Fire Service Installation Contractors for 2 months | G.N. 544 | https://www.gld.gov.hk/egazette/pdf/20222604/egn20222604544.pdf |
| Man Leong Fire Services Limited | RC1/0371 RC2/0530 | 15.1.2022 – 14.3.2022 | Removed from the registers of Class 1 and Class 2 Fire Service Installation Contractors for 2 months | G.N. 542 | https://www.gld.gov.hk/egazette/pdf/20222604/egn20222604542.pdf |
| China Status Development and Engineering Company Limited | RC1/0466 RC2/0637 | 15.1.2022 – 4.2.2022 | Removed from the registers of Class 1 and Class 2 Fire Service Installation Contractors for 3 weeks | G.N. 541 | https://www.gld.gov.hk/egazette/pdf/20222604/egn20222604541.pdf |
| Kin Ying Contracting Limited | RC1/0383 RC2/0544 | 15.1.2022 – 28.1.2022 | Removed from the registers of Class 1 and Class 2 Fire Service Installation Contractors for 2 weeks | G.N. 540 | https://www.gld.gov.hk/egazette/pdf/20222604/egn20222604540.pdf |
| HUI Ham-so | RC3/0175 | 15.1.2022 – 14.5.2022 | Removed from the register of Class 3 Fire Service Installation Contractors for 4 months | G.N. 543 | https://www.gld.gov.hk/egazette/pdf/20222604/egn20222604543.pdf |

**Record of Orders made by the
Registered Fire Service Installation Contractors Disciplinary Board for the Past 5 Years**

| Name of Registered Fire Service Installation Contractor | Class / Registration No. | Effective Date of Order | Order | Government Notice No. | Link to Government Notice |
|--|---------------------------------|--------------------------------|--|------------------------------|---|
| F.S. Engineering Co. Ltd. | RC1/0386 RC2/0548 | 11.1.2022 – 10.4.2022 | Removed from the registers of Class 1 and Class 2 Fire Service Installation Contractors for 3 months | G.N. 394 | https://www.gld.gov.hk/egazette/pdf/20222603/egn20222603394.pdf |
| FM Engineering Company Limited | RC1/0445 RC2/0617 | 11.1.2022 – 10.3.2022 | Removed from the registers of Class 1 and Class 2 Fire Service Installation Contractors for 2 months | G.N. 391 | https://www.gld.gov.hk/egazette/pdf/20222603/egn20222603391.pdf |
| CHAN King-sum | RC3/0819 | 11.1.2022 – 10.3.2022 | Removed from the register of Class 3 Fire Service Installation Contractors for 2 months | G.N. 393 | https://www.gld.gov.hk/egazette/pdf/20222603/egn20222603393.pdf |
| Kin Shun Co. Ltd. | RC1/0207 RC2/0352 | 11.1.2022 – 10.3.2022 | Removed from the registers of Class 1 and Class 2 Fire Service Installation Contractors for 2 months | G.N. 392 | https://www.gld.gov.hk/egazette/pdf/20222603/egn20222603392.pdf |
| Wai Lun Engineering Co. Ltd. | RC2/0528 | 11.1.2022 – 10.3.2022 | Removed from the register of Class 2 Fire Service Installation Contractors for 2 months | G.N. 390 | https://www.gld.gov.hk/egazette/pdf/20222603/egn20222603390.pdf |
| Chun Wo E & M Engineering Limited | RC1/0357 RC2/0581 | 4.6.2021 – 3.9.2021 | Removed from the registers of Class 1 and Class 2 Fire Service Installation Contractors for 3 months | G.N. 3686 | https://www.gld.gov.hk/egazette/pdf/20212524/egn202125243686.pdf |
| Ted Engineering Limited | RC1/0113 RC2/0244 | 4.6.2021 – 3.8.2021 | Removed from the registers of Class 1 and Class 2 Fire Service Installation Contractors for 2 months | G.N. 3687 | https://www.gld.gov.hk/egazette/pdf/20212524/egn202125243687.pdf |

**Record of Orders made by the
Registered Fire Service Installation Contractors Disciplinary Board for the Past 5 Years**

| Name of Registered Fire Service Installation Contractor | Class / Registration No. | Effective Date of Order | Order | Government Notice No. | Link to Government Notice |
|--|---------------------------------|--------------------------------|--|------------------------------|---|
| S & L Engineering Services Limited | RC1/0141 RC2/0270 | 4.6.2021 – 3.8.2021 | Removed from the registers of Class 1 and Class 2 Fire Service Installation Contractors for 2 months | G.N. 3688 | https://www.gld.gov.hk/egazette/pdf/20212524/egn202125243688.pdf |
| Sun Yip Engineering Company | RC1/0338 RC2/0492 | 4.6.2021 – 3.8.2021 | Removed from the registers of Class 1 and Class 2 Fire Service Installation Contractors for 2 months | G.N. 3689 | https://www.gld.gov.hk/egazette/pdf/20212524/egn202125243689.pdf |
| Rich Engineering Limited | RC1/0175 RC2/0312 | 16.2.2021 – 1.3.2021 | Removed from the registers of Class 1 and Class 2 Fire Service Installation Contractors for 2 weeks | G.N. 1372 | https://www.gld.gov.hk/egazette/pdf/20212510/egn202125101372.pdf |
| Shun Cheong Electrical Engineering Company Limited | RC1/0030 RC2/0067 | 1.1.2021 – 11.2.2021 | Removed from the registers of Class 1 and Class 2 Fire Service Installation Contractors for 6 weeks | G.N. 473 | https://www.gld.gov.hk/egazette/pdf/20212504/egn20212504473.pdf |
| Man Lick Engineering and Trading Company Limited | RC1/0138 RC2/0109 | 25.12.2020 – 24.2.2021 | Removed from the registers of Class 1 and Class 2 Fire Service Installation Contractors for 2 months | G.N. 180 | https://www.gld.gov.hk/egazette/pdf/20212502/egn20212502180.pdf |
| Century Fire Service Engineering Co. Limited | RC1/0389 RC2/0554 | 25.12.2020 – 24.3.2021 | Removed from the registers of Class 1 and Class 2 Fire Service Installation Contractors for 3 months | G.N. 181 | https://www.gld.gov.hk/egazette/pdf/20212502/egn20212502181.pdf |
| New Extend Engineering Limited | RC1/0441 RC2/0614 | 25.12.2020 – 24.3.2021 | Removed from the registers of Class 1 and Class 2 Fire Service Installation Contractors for 3 months | G.N. 182 | https://www.gld.gov.hk/egazette/pdf/20212502/egn20212502182.pdf |

**Record of Orders made by the
Registered Fire Service Installation Contractors Disciplinary Board for the Past 5 Years**

| Name of Registered Fire Service Installation Contractor | Class / Registration No. | Effective Date of Order | Order | Government Notice No. | Link to Government Notice |
|--|---------------------------------|--------------------------------|--|------------------------------|---|
| Yiu Lam Engineering Services Company Limited | RC1/0409 RC2/0579 | 25.12.2020 – 24.2.2021 | Removed from the registers of Class 1 and Class 2 Fire Service Installation Contractors for 2 months | G.N. 183 | https://www.gld.gov.hk/egazette/pdf/20212502/egn20212502183.pdf |
| LEUNG Kam-hing | RC3/0718 | 25.12.2020 – 24.2.2021 | Removed from the register of Class 3 Fire Service Installation Contractors for 2 months | G.N. 184 | https://www.gld.gov.hk/egazette/pdf/20212502/egn20212502184.pdf |
| Mansion Fire Services Company Limited | RC1/0271 RC2/0414 | 25.12.2020 – 4.2.2021 | Removed from the registers of Class 1 and Class 2 Fire Service Installation Contractors for 6 weeks | G.N. 185 | https://www.gld.gov.hk/egazette/pdf/20212502/egn20212502185.pdf |
| Shinryo Technical Services Limited | RC1/0536 RC2/0710 | 25.12.2020 – 24.2.2021 | Removed from the registers of Class 1 and Class 2 Fire Service Installation Contractors for 2 months | G.N. 186 | https://www.gld.gov.hk/egazette/pdf/20212502/egn20212502186.pdf |
| SO Yung-chung and FU Chi-tung trading as Grand Hope Fire Plumbing Electrical Engineering Co. | RC1/0231 RC2/0377 | 25.12.2020 – 7.1.2021 | Removed from the registers of Class 1 and Class 2 Fire Service Installation Contractors for 2 weeks | G.N. 188 | https://www.gld.gov.hk/egazette/pdf/20212502/egn20212502188.pdf |
| Token Engineering Limited | RC1/0345 RC2/0502 | 25.12.2020 – 24.6.2021 | Removed from the registers of Class 1 and Class 2 Fire Service Installation Contractors for 6 months | G.N. 187 | https://www.gld.gov.hk/egazette/pdf/20212502/egn20212502187.pdf |
| HUI Ham-so | RC3/0175 | 15.10.2019 – 25.11.2019 | Removed from the register of Class 3 Fire Service Installation Contractors for 6 weeks | G.N. 6902 | https://www.gld.gov.hk/egazette/pdf/20192345/egn201923456902.pdf |

**Record of Orders made by the
Registered Fire Service Installation Contractors Disciplinary Board for the Past 5 Years**

| Name of Registered Fire Service Installation Contractor | Class / Registration No. | Effective Date of Order | Order | Government Notice No. | Link to Government Notice |
|--|---------------------------------|--------------------------------|--|------------------------------|---|
| Fita (International) Fire Prevention Engineering Limited | RC1/0176 RC2/0313 | 4.10.2019 – 3.12.2019 | Removed from the registers of Class 1 and Class 2 Fire Service Installation Contractors for 2 months | G.N. 6903 | https://www.gld.gov.hk/egazette/pdf/20192345/egn201923456903.pdf |
| Chun Wo E & M Engineering Limited | RC1/0357 RC2/0581 | 3.10.2019 – 2.12.2019 | Removed from the registers of Class 1 and Class 2 Fire Service Installation Contractors for 2 months | G.N. 6904 | https://www.gld.gov.hk/egazette/pdf/20192345/egn201923456904.pdf |
| Best Engineering Services Limited | RC1/0390 RC2/0555 | 3.10.2019 – 2.2.2020 | Removed from the registers of Class 1 and Class 2 Fire Service Installation Contractors for 4 months | G.N. 6905 | https://www.gld.gov.hk/egazette/pdf/20192345/egn201923456905.pdf |
| Safety Fire Engineering Limited | RC2/0655 | 3.11.2018 | Reprimanded | G.N. 8639 | https://www.gld.gov.hk/egazette/pdf/20182246/egn201822468639.pdf |
| HUI HAM SO trading as Sun Tai Company | RC2/0602 | 29.10.2018 – 28.4.2019 | Removed from the register of Class 2 Fire Service Installation Contractors for 6 months | G.N. 8641 | https://www.gld.gov.hk/egazette/pdf/20182246/egn201822468641.pdf |
| East Power Engineering Limited | RC1/0309 RC2/0459 | 29.10.2018 | Reprimanded | G.N. 8640 | https://www.gld.gov.hk/egazette/pdf/20182246/egn201822468640.pdf |
| American Fire Engineering Limited | RC1/0259 RC2/0405 | 25.10.2018 – 7.11.2018 | Removed from the registers of Class 1 and Class 2 Fire Service Installation Contractors for 14 days | G.N. 8636 | https://www.gld.gov.hk/egazette/pdf/20182246/egn201822468636.pdf |
| Huns Engineering Company Limited | RC1/0414 RC2/0587 | 25.10.2018 | Reprimanded | G.N. 8637 | https://www.gld.gov.hk/egazette/pdf/20182246/egn201822468637.pdf |

**Record of Orders made by the
Registered Fire Service Installation Contractors Disciplinary Board for the Past 5 Years**

| Name of Registered Fire Service Installation Contractor | Class / Registration No. | Effective Date of Order | Order | Government Notice No. | Link to Government Notice |
|--|---------------------------------|--------------------------------|---|------------------------------|---|
| Technic Engineers Company | RC1/0118 RC2/0195 | 25.10.2018 – 31.10.2018 | Removed from the registers of Class 1 and Class 2 Fire Service Installation Contractors for 7 days | G.N. 8638 | https://www.gld.gov.hk/egazette/pdf/20182246/egn201822468638.pdf |
| Smart Ocean Engineering Limited | RC1/0308 RC2/0458 | 28.6.2018 -11.7.2018 | Removed from the registers of Class 1 and Class 2 Fire Service Installation Contractors for 14 days | G.N. 6032 | https://www.gld.gov.hk/egazette/pdf/20182232/egn201822326032.pdf |
| Starberg Limited | RC1/0197 RC2/0340 | 28.6.2018 -4.7.2018 | Removed from the registers of Class 1 and Class 2 Fire Service Installation Contractors for 7 days | G.N. 6033 | https://www.gld.gov.hk/egazette/pdf/20182232/egn201822326033.pdf |
| CHUN Lai-ming | RC3/0731 | 27.1.2018 -2.2.2018 | Removed from the register of Class 3 Fire Service Installation Contractors for 7 days | G.N. 755 | https://www.gld.gov.hk/egazette/pdf/20182206/egn20182206755.pdf |
| LAW Kwai-sheung | RC3/0574 | 23.1.2018 | Reprimanded | G.N. 749 | https://www.gld.gov.hk/egazette/pdf/20182206/egn20182206749.pdf |
| New Extend Engineering Ltd | RC1/0441 RC2/0614 | 23.1.2018 -5.2.2018 | Removed from the registers of Class 1 and Class 2 Fire Service Installation Contractors for 14 days | G.N. 750 | https://www.gld.gov.hk/egazette/pdf/20182206/egn20182206750.pdf |
| Fook Cheong Engineering (HK) Ltd | RC1/0222 RC2/0366 | 23.1.2018 -29.1.2018 | Removed from the registers of Class 1 and Class 2 Fire Service Installation Contractors for 7 days | G.N. 751 | https://www.gld.gov.hk/egazette/pdf/20182206/egn20182206751.pdf |

**Record of Orders made by the
Registered Fire Service Installation Contractors Disciplinary Board for the Past 5 Years**

| Name of Registered Fire Service Installation Contractor | Class / Registration No. | Effective Date of Order | Order | Government Notice No. | Link to Government Notice |
|--|---------------------------------|--------------------------------|---|------------------------------|---|
| Fook Cheong Engineering (HK) Ltd | RC1/0222 RC2/0366 | 23.1.2018 | Reprimanded | G.N. 752 | https://www.gld.gov.hk/egazette/pdf/20182206/egn20182206752.pdf |
| Penta-Fire Engineering Ltd | RC1/0367 RC2/0522 | 23.1.2018 -5.2.2018 | Removed from the registers of Class 1 and Class 2 Fire Service Installation Contractors for 14 days | G.N. 753 | https://www.gld.gov.hk/egazette/pdf/20182206/egn20182206753.pdf |
| Chevalier (E&M Contracting) Ltd | RC2/0228 | 23.1.2018 | Reprimanded | G.N. 754 | https://www.gld.gov.hk/egazette/pdf/20182206/egn20182206754.pdf |